AMENDMENTS TO THE SPECIFICATION

In the Specification:

Please **AMEND** the specification as shown in the following marked up paragraph, which shows changes made relative to the immediate prior version.

Please **AMEND** the paragraph beginning on page 10, line 11 as follows:

As described above, the current interrupter 36a, which is a region of the negative electrode lead 36, causes a disconnection when there is an increase in <u>currentresistance</u>. Thus, it is important to select an appropriate material for the current interrupter 36a and the negative electrode lead 36. Materials, such as, copper, nickel or an alloy thereof may be used.